



Dart Aerospace Ltd.
1270 Aberdeen St
Hawkesbury, ON
K6A 1K7
Canada

Tel (613) 632-5200
Fax 613 632-5246

D5325-5

Job Sheet 200519



16 pcs.
Dr
[Signature]

Part No: D5325-5

Job Qty: 4 pcs

Part Name: Foot



Part Weight: 0 lbs

Status: New

Priority: Medium

Job Created: 9/12/19

Job Tracking No:

Due Date: 10/4/19

Created By: Marie Lajeunesse

Type: Stock *Stop*

Description:

Note: DWG REV B SHEET 5 IPP REV:A 15.12.15 NEW ISSUE DD VERF:JLM

Ship Via:

Bill of Materials

Job Routing

Op No	Operation	Qty	Start Date	Due Date	Standard		Workcenter/Supplier		Sign-off
					Setup Hrs	Run Hrs	Workcenter / Supplier	Lead Time	
110	Bandsaw - 1	4 pcs	10/4/19	10/4/19	0.00	0.30	Bandsaw - 1		<i>Kt 19-09-18</i>
120	Conventional Mill - 1 - B4B	4 pcs	10/4/19	10/4/19	0.00	3.39	Conventional Mill - 1 - B4B		
							Conventional Mill - 2 - B4B		<i>Kt 19-09-18</i>
130	QC 2	4 pcs	10/4/19	10/4/19	0.00	0.00	QC 2 - 1		<i>Kt 19-09-18</i>
							QC 2 - 12		
							QC 2 - 14		
							QC 2 - 17		
							QC 2 - 19		
							QC 2 - 2		
							QC 2 - 20		
							QC 2 - 22		
							QC 2 - 23		
							QC 2 - 25		
							QC 2 - 32		
							QC 2 - 33		
							QC 2 - 35		
							QC 2 - 39		
							QC 2 - 4		
							QC 2 - 40		
							QC 2 - 44		
							QC 2 - 45		
							QC 2 - 48		
							QC 2 - 49		
							QC 2 - 50		
							QC 2 - 51		
							QC 2 - 52		
							QC 2 - 57		
							QC 2 - 62		
							QC 2 - 63		
							QC 2 - 8		
							QC 2 - 66		



Dart Aerospace Ltd.
1270 Aberdeen Street
Hawkesbury, ON K6A 1K7
CANADA
TEL.: 1 613 632-5200
Email: sales@dartaero.com
www.dartaerospace.com

Container No: S214754



Part: D5325-5

Job No: 200519

Serial No/Batch: S214754

Revision:

Inspector:

Exp Date:

Instructions: Various STC's

Date: 09/10/19

140 QC 8	4 pcs	10/4/19	0.00 0.00	QC 2 - 64	
				QC 2 - 65	
				QC 2 - 5	
				QC 2 - 71	
				QC 2 - 73	
				QC 2 - 69	
				QC 8 - 12	
				QC 8 - 14	
				QC 8 - 17	
				QC 8 - 20	
				QC 8 - 25	
				QC 8 - 3	
				QC 8 - 32	
				QC 8 - 33	
				QC 8 - 35	
				QC 8 - 39	
				QC 8 - 4	
				QC 8 - 44	
				QC 8 - 45	
				QC 8 - 49	
				QC 8 - 58	
				QC 8 - 8	
				QC 8 - 9	
				QC 8 - 68	
				QC 8 - 67	
				QC 8 - 1 (A)	
				QC 8 - 47	
				QC 8 - 40	
				QC 8 - 52	
				QC 8 - 23	
				QC 8 - 57	
				QC 8 - 76	
150 Packaging 3-1 - Stock - B4B 4 pcs		10/4/19	0.00 0.00	Packaging 3 - 1 - B4B	
				Packaging 3 - 2 - B4B	
				Packaging 3 - 3 - B4B	
				Packaging 3 - 4 - B4B	
				Packaging 3 - 5 - B4B	
				Packaging 3 - 6 - B4B	
				Packaging 3 - 7 - B4B	
				Packaging 3 - 8 - B4B	
				Packaging 3 - 9 - B4B	
				Packaging 3 - 10 - B4B	
				Packaging 3 - 11 - B4B	
				Packaging 3 - 12 - B4B	
				Packaging 3 - 13 - B4B	
				Packaging 3 - 14 - B4B	
				Packaging 3 - 15 - B4B	
				Packaging 3 - 16 - B4B	
				Packaging 3 - 17 - B4B	
				Packaging 3 - 18 - B4B	DAS
				Packaging 3 - 19 - B4B	43
				Packaging 3 - 20 - B4B	9-80
				Packaging 3 - 21 - B4B	
				Packaging 3 - 22 - B4B	
				Packaging 3 - 23 - B4B	
				Packaging 3 - 24 - B4B	
				Packaging 3 - 25 - B4B	
				Packaging 3 - 26 - B4B	
				Packaging 3 - 27 - B4B	

				Packaging 3 - 28 - B4B	
				Packaging 3 - 29 - B4B	
				Packaging 3 - 30 - B4B	
				Packaging 3 - 31 - B4B	
				Packaging 3 - 32 - B4B	
				Packaging 3 - 33 - B4B	
				Packaging 3 - 34 - B4B	
				Packaging 3 - 35 - B4B	
				Packaging 3 - 36 - B4B	
160 QC 21 - SA	4 pcs	10/4/19	0.00 0.00	QC 21 - SA - 21	21
				QC 21 - SA - 70	9-39
				QC 21 - SA - 53	
Part Op 110 - (Bandsaw) Cut blank at 1.90" Descriptions: 120 - (Manufacture as per dwg) USE DT10216 TO MILL 45DEG 130 - (QC2- Inspect parts off machine FAI/FAIB) 140 - (QC8- Inspect parts - second check) 150 - (Identify as per dwg & Stock Location: _____) LOCATION: WA004-3 160 - (QC21- Final Inspection - Work Order Release)					
Job BOM					
Part / Item	Component Name	Quantity	Operation	Container	
M304B0.500X0.500	304 Bar .500 X .500	.6320 ft (.158 ea)	110-Bandsaw - 1	51446A	
Job Allocations					
Operation	Component Part	Required	Inventory	Allocated	
110-Bandsaw - 1	M304B0.500X0.500	1	570	0	
Part Specifications					
Specifications could not be found.					

Plex 9/12/19 9:53 AM Dart.lajeunesse.marie




Entered: _____ Date: _____

WORK ORDER NON-CONFORMANCE / ROUTE UPDATE

NCR No. _____

Route update only ☐

Job: _____ Part No. _____		DISPOSITION		DEPARTMENT/PROCESS																																																																																	
		Rework ☐	Skid-tube ☐	Cross tube ☐	Eng. (Non-AW) ☐																																																																																
		Scrap ☐	Machining ☐	Small Fab ☐	Prod. Eng. Coord. ☐																																																																																
		Use-as-is ☐	Large Fab ☐	Finishing ☐	Rec/Store/Packaging ☐																																																																																
Date: _____		Sequence #: _____		QTY Affected: _____																																																																																	
Description Work Order Deviation		Disposition																																																																																			
Root Cause <table border="1"><tr><td>Operator</td><td>☐</td></tr><tr><td>Manufacturing Process</td><td>☐</td></tr><tr><td>Equip/Tooling</td><td>☐</td></tr><tr><td>Handling/Preservation</td><td>☐</td></tr><tr><td>Material</td><td>☐</td></tr><tr><td>Product Improvement</td><td>☐</td></tr><tr><td>Process Improvement</td><td>☐</td></tr><tr><td>Human Factors</td><td>☐</td></tr></table>		Operator	☐	Manufacturing Process	☐	Equip/Tooling	☐	Handling/Preservation	☐	Material	☐	Product Improvement	☐	Process Improvement	☐	Human Factors	☐	FAULT CATEGORY <table border="1"><tr><td>Pressure/Forced</td><td>☐</td><td>Contamination</td><td>☐</td><td>Power Loss/Surge</td><td>☐</td><td>Positioned Wrong</td><td>☐</td></tr><tr><td>Bending</td><td>☐</td><td>Misaligned/off center</td><td>☐</td><td>Folio/Program</td><td>☐</td><td>Outside Tolerance</td><td>☐</td></tr><tr><td>Crushing</td><td>☐</td><td>BOM/Route</td><td>☐</td><td>Grain Direction</td><td>☐</td><td>Drawing</td><td>☐</td></tr><tr><td>Cracks</td><td>☐</td><td>Broken/Damage/Defect</td><td>☐</td><td>Weld</td><td>☐</td><td>Finish</td><td>☐</td></tr><tr><td>Crimp/Kink/Ripple/Wave/Twist</td><td>☐</td><td>Incomplete/Unclear Instructions</td><td>☐</td><td>Wrong Stock Pulled</td><td>☐</td><td>Part Lost/Missing</td><td>☐</td></tr><tr><td>Marks/Chatter</td><td>☐</td><td>Drill Holes</td><td>☐</td><td>Out of Sequence</td><td>☐</td><td>Misread</td><td>☐</td></tr><tr><td>Mislabeled</td><td>☐</td><td>Fit/Function</td><td>☐</td><td>Off-set/Set-up</td><td>☐</td><td></td><td></td></tr><tr><td colspan="2">Other/Details:</td><td colspan="6"></td></tr></table>				Pressure/Forced	☐	Contamination	☐	Power Loss/Surge	☐	Positioned Wrong	☐	Bending	☐	Misaligned/off center	☐	Folio/Program	☐	Outside Tolerance	☐	Crushing	☐	BOM/Route	☐	Grain Direction	☐	Drawing	☐	Cracks	☐	Broken/Damage/Defect	☐	Weld	☐	Finish	☐	Crimp/Kink/Ripple/Wave/Twist	☐	Incomplete/Unclear Instructions	☐	Wrong Stock Pulled	☐	Part Lost/Missing	☐	Marks/Chatter	☐	Drill Holes	☐	Out of Sequence	☐	Misread	☐	Mislabeled	☐	Fit/Function	☐	Off-set/Set-up	☐			Other/Details:							
		Operator	☐																																																																																		
		Manufacturing Process	☐																																																																																		
Equip/Tooling	☐																																																																																				
Handling/Preservation	☐																																																																																				
Material	☐																																																																																				
Product Improvement	☐																																																																																				
Process Improvement	☐																																																																																				
Human Factors	☐																																																																																				
Pressure/Forced	☐	Contamination	☐	Power Loss/Surge	☐	Positioned Wrong	☐																																																																														
Bending	☐	Misaligned/off center	☐	Folio/Program	☐	Outside Tolerance	☐																																																																														
Crushing	☐	BOM/Route	☐	Grain Direction	☐	Drawing	☐																																																																														
Cracks	☐	Broken/Damage/Defect	☐	Weld	☐	Finish	☐																																																																														
Crimp/Kink/Ripple/Wave/Twist	☐	Incomplete/Unclear Instructions	☐	Wrong Stock Pulled	☐	Part Lost/Missing	☐																																																																														
Marks/Chatter	☐	Drill Holes	☐	Out of Sequence	☐	Misread	☐																																																																														
Mislabeled	☐	Fit/Function	☐	Off-set/Set-up	☐																																																																																
Other/Details:																																																																																					
Completed By				MRB (QSI042)																																																																																	
Lead hand / Supervisor																																																																																					
QC / QA Coordinator																																																																																					



1771

D5325-5 FOOT

- NOTES:
- 1) MATERIAL: AISI 304/316 SS BAR OR AISI 304/316 SS PLATE
PER ASTM A276 OR ASTM A240
REF DART SPEC. M304B
 - 2) FINISH: NONE
 - 3) TOLERANCES: PER DART OSI 018 UNLESS OTHERWISE NOTED
 - 4) UNITS: INCHES UNLESS OTHERWISE NOTED
 - 5) BREAK SHARP EDGES: 0.005 TO 0.010 MAX
 - 6) IDENTIFICATION: N/A
 - 7) WEIGHT: 0.08 lbs

RELEASED
2017-03-22

DESIGN	RF	RF	DART AEROSPACE LTD
DRAWN	RF	RF	HAWKESBURY, ONTARIO, CANADA
CHECKED	VS	VS	DRAWING NO. D5325
MFG. APPR.	DD	DD	REV. B SHEET 5 OF 5
APPROVED	HS	HS	TITLE RIB ASSEMBLY
DE APPR.	DS	DS	SCALE NTS
DATE	17.02.09		

COPYRIGHT © 2015 BY DART AEROSPACE LTD
THIS DRAWING IS THE PROPERTY OF DART AEROSPACE LTD
IT IS TO BE USED FOR ANY PURPOSES WITHOUT THE WRITTEN PERMISSION OF DART AEROSPACE LTD